

BellSouth Corporation
Suite 900
1133-21st Street N.W.
Washington, D.C. 20036-3351

mary.henze@bellsouth.com

RECEIVED

NOV 12 2002

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Mary L. Henze
Executive Director
Federal Regulatory Affairs

202 463 4109
Fax 202 463 4631

November 12, 2002

Ms. Marlene H. Dortch
Secretary
Federal Communications Commission
445 Twelfth Street, S.W.
Washington, DC 20554

Re: Notices of Network Change Under Rule 51.329(a) CC Docket No. 96-98

Dear Ms. Dortch:


BellSouth Telecommunications, Inc. ("BellSouth") hereby submits the attached original and two copies of its Notices of Network Change Under Rule 51.329(a) in accordance with the requirements set forth in the Commission's Second Report and Order and Memorandum Opinion and Order released August 8, 1996, in CC Docket No. 96-98. A description of the network change is provided below:

Number	Type of Change Planned	Location of Change
91083387	Replacing Copper with Fiber	Ft. Kenton, Kentucky
91083392	Central Office Conversion	Benoit, Mississippi
91083395	Replacing Copper with Fiber	Holtville, Alabama
91083398	Replacing Copper with Fiber	Shreveport, LA
91083399	Replacing Copper with Fiber	Shreveport, LA
91083400	Replacing Copper with Fiber	Shreveport, LA
91083401	Replacing Copper with Fiber	Shreveport, LA
91083403	Replacing Copper with Fiber	Killen, Alabama
91083404	Replacing Copper with Fiber	Leighton, Alabama
91083405	Replacing Copper with Fiber	Lexington, Alabama

As required, one paper copy and one diskette copy is being submitted to the Chief of the Common Carrier Bureau's Network Services Division. A copy of the notice is also available at:
<http://www.interconnection.bellsouth.com/notifications/networldindex.html>

Should you have any questions regarding this submission, please contact me at (202) 463-4109.

Sincerely,



Mary L. Henze
Executive Director - Federal Regulatory

Attachments

cc: Michelle Carey (with diskette)

Carmell Weathers (with diskette)

Notice of Network Change - Fegenbush Lane, Kentucky
Replacing Copper Facilities **with** Fiber and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Ending 2nd Quarter 2003

Location of Changes: Fegenbush Ln from Outer Loop to Vaughn Mill Rd, including Michael Dr, Briscoe Ln, Elsie Ct, Arthur Goins Blvd, Juanita Goins Ct, Highview Dr, Layman Dr, Stovall Pl, & Stovall Ct

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has **no** basis to notify the carrier and there will be no means to continue the DSL service.

Contact:	<u>Technical questions</u>	Ben Cook, Loop Capacity Manager
	relating to this change	3719 Bardstown Rd
	should be directed to:	Louisville, KY 40299
		502-454-9588

All other questions or concerns regarding this change should ~~be~~ referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory IO-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change - Benoit, Mississippi Central Office Conversion

Carrier
BellSouth Telecommunications, Inc
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Saturday, May 17, 2003, 12:01 AM Central Daylight Time

Location of Changes: Benoit, Mississippi

Description of Change Planned: Benoit, Mississippi Central Office Conversion: The Siemens Stromberg-Carlson RLS4000 remote switch (BNITMSMADS1) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) will be BNITMSMARS9 and the new point code will be 252-146-099. The new switch will be a remote working from the Cleveland Host (CLEVMSMADS2). The following NXX code(s) will be affected with this conversion:

Area Code: 662 NXX: 742

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting Carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide Interconnecting Carriers with Trunk Group Service Request (TGSr) forms that must be returned to BellSouth by the Response Due Date provided on the TGSr. Interconnecting Carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSrs that are returned to BellSouth and submit their ASRs by the TGSr Response Due Date.

A service order freeze will be in effect from Friday, May 9, 2003 through Sunday, May 18, 2003. Therefore, scheduling Point of Presence (POP) moves, major Trunking rearrangements, translation changes, or critical dates should be avoided during this period.

In addition, customers in the affected area will have immediate access to Pay Per-Use features.

Contact: Technical questions Karl Donnelly or Robert Cheadle, Managers - Network
relating to this change 6767 Bundy Road, First Floor North
should be directed to: New Orleans, Louisiana 70127
504-248-7727 or 504-248-7724

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change Under Rule 51.329(a)
Notification No. SN91083392
Issue Date: November 5, 2002

Notice of Network Change • Holtville, Alabama
Replacing Copper Facilities with **Fiber** and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Third Quarter 2003

Location of Changes: Holtville, Alabama – Carrier Serving Area 1206A – Distribution Area currently served by cable 105 in the vicinity of Possum Trot Rd (heading northwest of the intersection of Possum Trot Rd and Gamer Rd) and along Shoal Creek Rd

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: Technical questions Mendolyn Foster, Loop Capacity Manager
relating to this change 10494 Highway 80 E
should be directed to: Montgomery, AL 36117
334- 244-6108

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change – Shreveport, LA
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: 3rd Quarter 2003

Location of Changes: 3151 N Market St-RT CLLI SHPTLAU1153

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems crossing 12 Mile Bayou Bridge.

Description of Reasonably Foreseeable Impact of the Planned Change: Circuits working on unbundled copper loops in this area will need to be moved off the copper cables by July 1, 2003. Requests for new copper loops in this area will not be accepted. After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: Technical questions Michael H. Sinclair
relating to this change 3115 Dee Street RM 134
should be directed to: Shreveport, LA 71105
318-670-1002

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change – Shreveport, LA
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier

BellSouth Telecommunications, Inc
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: 3rd Quarter 2003

Location of Changes: 4047 N Market St-RT CLLI SHPTLANMW01

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems crossing 12 Mile Bayou Bridge.

Description of Reasonably Foreseeable Impact of the Planned Change: Circuits working on unbundled copper loops in this area will need to be moved off the copper cables by July 1, 2003. Requests for new copper loops in this area will not be accepted. After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: <u>Technical questions</u> relating to this change should be directed to:	Michael H. Sinclair 3115 Dee Street RM 134 Shreveport, LA 71105 318-670-1002
---	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region:	557-2647 (AL, KY, LA, MS, TN) or 780-2171 (FL, GA, NC, SC) (If you are calling from a mandatory IO-digit calling area, include your local area code.)
--------------------------	--

Outside BellSouth region:	1-800-786-7619
Fax:	1-205-321-2191

Notice of Network Change – Shreveport, LA
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: 3rd Quarter 2003

Location of Changes: 4925 Hwy 538-RT CLLI SHPTLAU8884

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems crossing 12 Mile Bayou Bridge.

Description of Reasonably Foreseeable Impact of the Planned Change: Circuits working on unbundled copper loops in this area will need to be moved off the copper cables by July 1, 2003. Requests for new copper loops in this area will not be accepted. After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact:	<u>Technical questions</u>	Michael H. Sinclair
	relating to this change	3115 Dee Street RM 134
	should be directed to:	Shreveport, LA 71105
		318-670-1002

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change – Shreveport, LA
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: 3rd Quarter 2003

Location of Changes: 5516 Alan Street-RT CLLI SHPTLAU9500

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems crossing 12 Mile Bayou Bridge.

Description of Reasonably Foreseeable Impact of the Planned Change: Circuits working on unbundled copper loops in this area will need to be moved off the copper cables by July 1, 2003. Requests for new copper loops in this area will not be accepted. After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service. BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: <u>Technical questions</u>	Michael H. Sinclair
relating to this change	3115 Dee Street RM 134
should be directed to:	Shreveport, LA 71105
	318-670-1002

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory IO-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change • Killen, Alabama
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Second Quarter 2003

Location of Changes: Killen, AL- In the area of Highway 72 East and Mitchell Town Road: north on Mitchell Town Rd (County Rd 33) for 1 ½ miles, east on Hwy 72 to wire center boundary, all points south of Hwy 72 in Houstontown Rd area (County Rd 33).

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems.

Description of Reasonably ~~Foreseeable~~ Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: Technical questions relating to this change **should** be directed to: Amber Owens, Loop Capacity Manager
425 Grant St
Decatur, AL 35601
256-552-7134

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change • Leighton, Alabama
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Third Quarter 2003

Location of Changes: Leighton, AL- County Line Rd (County Rd 48), all areas south of, but not including, Poplar Creek Circle, to southern wire center boundary. RT CLLI LGTNALU0030.

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: Technical questions Amber Owens, Loop Capacity Manager
relating to this change 425 Grant St
should be directed to: Decatur, AL 35601
256-552-7134

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change • Lexington, Alabama
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Third Quarter 2003

Location of Changes: Lexington, AL- In the area of Alabama Hwy 64 E, all areas east of Lauderdale Co. Rd 89. RT CLLIs LXTNALU0001 & LXTNALU0016.

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC). e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: Technical questions Amber Owens, Loop Capacity Manager
relating to this change 425 Grant St
should be directed to: Decatur, AL 35601
256-552-7134

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory IO-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191